Practice tips for the safe processing of lead sheet







Always wear gloves: they protect against injuries and offer a better grip.



A suitable hand cleaner is mandatory



Eating and drinking is not permitted during work with lead.



Without running water: clean hands with heavy-duty wipes



Smokers may not take a cigarette break in between.



Always wear a dust mask when performing welding work.





Before starting the work apply a protective cream on the hands.



A dust mask is also needed when dismantling old lead sheets.



Always wash work clothes separate from other textiles.



Do not chew on finger nails. For safety reasons, always keep the nails short.



Always check whether the dust mask is clean. Use disposables as an alternative.



The blood lead content must be checked freq. for persons working with lead.



After work, clean the hands thoroughly with a brush.



Clean the nose or wipe the wouth with a tissue.



Never lift lead rolls on your own if the weight exceeds 25 kg.



Beards may prevent the tight fit of a dust mask.